

Hyundai VERNA
optional safety equipment

PRIMARY SAFETY

95%

Electronic Stability Control 8.0 max. 8

system name ESC

Driver Monitoring System 2.0 max. 2

system name Driver Attention Warning

Tyre Pressure Monitoring 2.0 max. 2

system name TPMS Highline

warning ●

readout ●

Blind Spot Monitoring 2.0 max. 2

system name Blind Spot Collision Warning

input rear corner radars

driver side ●

passenger side ●

Physical Controls 5.0 max. 6

hazard lights ●

gear ●

climate ●

music and navigation ●

turn indicators ●

windscreen wipers ●

SECONDARY SAFETY

50%

Rear Seatbelts 4.0 max. 4

position	outboard	centre	third row
three-point	●	●	○

Rear Seatbelt Reminders 2.0 max. 10

position	outboard	centre	third row
visual signal	●	●	○
acoustic signal	●	●	○
occupant detection	●	●	○
passive activation	●	●	○

Head Protection Devices 5.0 max. 6

position	front	rear	third row
curtain airbag	●	●	○
centre airbag	●	○	○

Chest Protection Devices 2.0 max. 3

position	front	rear
thorax airbag	●	●

Neck Restraints 0.0 max. 4

position	rear	outboard	centre	third row
sufficient ¹	●	●	●	○

Child Readiness 2.0 max. 3

position	rear	rear	front	third
	outboard	centre	passenger	row
ISOFIX	●	●	●	○
i-Size	●	●	●	○
Top Tether	●	●	●	○

COMMENTS

Results shown here are for a Verna with optional blind spot detection and driver monitoring, but the AC on/off switch is a capacitive touch button.

primary safety	secondary safety	overall result
95%	50%	
★★★★★	★★★★☆	★★★★☆
Evaluated variant: SX(O) 1.5 MPI IVT		
Evaluated on: September 12, 2025		
Protocol: FleetSure v1.0		

¹subjective judgment