Mahindra THAR ROXX

standard safety equipment





PRIMARY SAFETY

70%

Electronic Stability Control	8.0 max. 8
system name ES	С
Driver Monitoring System	0.0 max. 2
system name —	
Tyre Pressure Monitoring	0.0 max. 2
system name —	

warning readout

Blind Spot Monitoring **0.0** max. 2

> system name input

driver side passenger side

Physical Controls

6.0 max. 6

hazard lights

gear

climate

music and navigation

turn indicators

windscreen wipers

SECONDARY SAFETY

76%

Rear Seatbelts			4.0 max. 4
position	outboard	centre	third row
three-point			0

Rear Seatbeit Rer	ninders	10.	u max. 10
position	outboard	centre	third row
visual signal			0
acoustic signal			0
occupant detection	•		0
passive activation	•		0

Head Protection Devices		5.0 max. 6	
position	front	rear	third row
curtain airbag	•		0
centre airbag		0	0

Chest Protection Devices **2.0** max. 3 position front rear thorax airbag

Neck Restra	ints		0.0 max.	4
position	rear outboard	centre	third row	
$sufficient^1$		•	0	

Child Read	iness		2.0 r	max. 3
position	rear	rear	front	third
	outboard	centre	passenger	row
ISOFIX		•	•	0
i-Size			•	0
Top Tether		•	•	0

COMMENTS

The Thar is a popular rental; this result is for the 5-door Roxx. This result is not valid for the 3-door Than.

primary	secondary overall		
safety	safety	result	
70%	76%		

Evaluated variant : MX1 2.0 mStallion RWD MT			
Evaluated on: September 26, 2025			
Protocol: FleetSure v1.0			

¹subjective judgment